ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
YELAHANKA	9	Vidyaranyapura
Street ID	**Street Name**	**Significant Landmark**
W0482	4th Crs	Maramma Temple
Segment No.	**Total Length (m)**	
9/S-W0482/S112957	120.35	

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	120.35	77.572292	13.066257	77.573379	13.066038	Main Road	Cross Road

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Improvements and Asphalting to Roads at KVS Layout, 1st & 2nd Cross, Dhanalakshmi Layout in Ward No. 09 (Vidyaranyapura).	2000000	2019-20
Year	**Type of Work**	**Other Work Type**
2019 - 2020	Road	
Tender	**Work Details**	**Job No. / Work Code**
Tender	Asphalting to Roads	009-20-000085
Work Order No.	**Work Order Date**	**Period of Extention**
BBMP/EE/BTP/WO/22/2021-22	03/08/2021	
Defect Liability Period From	**Defect Liability Period To**	**Multiple road involved with the same Job No/ Work Code #**
25/04/2022	24/04/2023	No

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
M/s. SMLP Asphalts B.B. Umesha		0.00
Phone No.	**E-Mail ID**	
9886213563		

Assistant Executive Engineer
Vidyaranyapura Sub Division
B.B.M.P, Bangalore - 97

Field Inspection Details

Number of Trees	Any Other Information	Name
0		E Eranna
Date of Inspection	**Remarks**	
18/05/2022		

Category	Image	Photo Remark
Drain Condition		This photo seems out of range.
Footpath Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Segment End		This photo seems out of range.
Segment Start		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	S.P.Ranganath	18/05/2022	17/06/2022	As proposed
SE	G R Devendra Nayak	18/05/2022	17/06/2022	Forwarded
EE	Mohan Das H T	18/05/2022	17/06/2022	Forward
AEE	Shivakumar M Goudar	18/05/2022	17/06/2022	Verified
AE	E. Eranna	18/05/2022	17/06/2022	Mobile Verification Done
AE	E. Eranna	18/05/2022	17/06/2022	Forward

Assistant Executive Engineer
Vidyaranyapura Sub Division
B.B.M.P, Bangalore - 97

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
YELAHANKA	9	Vidyaranyapura
Street ID	**Street Name**	**Significant Landmark**
W0737	NA	Houses
Segment No.	**Total Length (m)**	
9/S-W0737/S113419	68.84	

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	68.84	77.572992	13.066108	77.572956	13.065487	1st Main	Dead End

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Improvements and Asphalting to Roads at KVS Layout, 1st & 2nd Cross, Dhanalakshmi Layout in Ward No. 09 (Vidyaranyapura).	2000000	2019-20
Year	**Type of Work**	**Other Work Type**
2019 - 2020	Road	
Tender	**Work Details**	**Job No. / Work Code**
Tender	Asphalting to Roads	009-20-000085
Work Order No.	**Work Order Date**	**Period of Extention**
BBMP/EE/BTP/WO/22/2021-22	03/08/2021	
Defect Liability Period From	**Defect Liability Period To**	**Multiple road involved with the same Job No/ Work Code #**
25/04/2022	24/04/2023	No

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
M/s. SMLP Asphalts B.B. Umesha		0.00
Phone No.	**E-Mail ID**	
9886213563		

Assistant Executive Engineer
Vidyaranyapura Sub Division
B.B.M.P, Bangalore - 97

Field Inspection Details

Number of Trees	Any Other Information	Name
0		E Eranna

Date of Inspection	Remarks
18/05/2022	

Category	Image	Photo Remark
Drain Condition		This photo seems out of range.
Footpath Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Segment End		This photo seems out of range.
Segment Start		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	S.P.Ranganath	18/05/2022	17/06/2022	As proposed
SE	G R Devendra Nayak	18/05/2022	17/06/2022	Forwarded
EE	Mohan Das H T	18/05/2022	17/06/2022	Forward
AEE	Shivakumar M Goudar	18/05/2022	17/06/2022	Verified
AE	E. Eranna	18/05/2022	17/06/2022	Mobile Verification Done
AE	E. Eranna	18/05/2022	17/06/2022	Forward

Assistant Executive Engineer
Vidyaranyapura Sub Division
B.B.M.P, Bangalore - 97

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
YELAHANKA	9	Vidyaranyapura
Street ID	**Street Name**	**Significant Landmark**
W0729	NA	Houses
Segment No.	**Total Length (m)**	
9/S-W0729/S113532	63.20	

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	63.20	77.572624	13.065592	77.572678	13.066161	1st Main	Dead End

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Improvements and Asphalting to Roads at KVS Layout, 1st & 2nd Cross, Dhanalakshmi Layout in Ward No. 09 (Vidyaranyapura).	2000000	2019-20
Year	**Type of Work**	**Other Work Type**
2019 - 2020	Road	
Tender	**Work Details**	**Job No. / Work Code**
Tender	Asphalting to Roads	009-20-000085
Work Order No.	**Work Order Date**	**Period of Extention**
BBMP/EE/BTP/WO/22/2021-22	03/08/2021	
Defect Liability Period From	**Defect Liability Period To**	**Multiple road involved with the same Job No/ Work Code #**
25/04/2022	24/04/2023	No

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
M/s. SMLP Asphalts B.B. Umesha		0.00
Phone No.	**E-Mail ID**	
9886213563		

Assistant Executive Engineer
Vidyaranyapura Sub Division
B.B.M.P, Bangalore - 97

Field Inspection Details

Number of Trees	Any Other Information	Name
0		E Eranna

Date of Inspection	Remarks
18/05/2022	

Category	Image	Photo Remark
Drain Condition		This photo seems out of range.
Footpath Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Segment End		This photo seems out of range.
Segment Start		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	S.P.Ranganath	18/05/2022	17/06/2022	As proposed
SE	G R Devendra Nayak	18/05/2022	17/06/2022	Forwarded
EE	H T Mohan Das	18/05/2022	17/06/2022	Forward
AEE	Shivakumar M Goudar	18/05/2022	17/06/2022	Verified
AE	E. Eranna	18/05/2022	17/06/2022	Mobile Verification Done
AE	E. Eranna	18/05/2022	17/06/2022	Forward

Zone: YELAHANKA **Ward No:** 9 **Ward Name:** Vidyaranyapura **Street ID:** W0729

Date: 18/05/2022 Time: 16:19:35 RH 20220518161935

Assistant Executive Engineer
Vidyaranyapura Sub Division
E.&.M.E, Bangalore - 97

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
YELAHANKA	9	Vidyaranyapura
Street ID	**Street Name**	**Significant Landmark**
W0490	NA	Houses
Segment No.	**Total Length (m)**	
9/S-W0490/S113642	50.81	

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	50.81	77.572157	13.065627	77.572624	13.065592	2nd Cross	Dead End

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Improvements and Asphalting to Roads at KVS Layout, 1st & 2nd Cross, Dhanalakshmi Layout in Ward No. 09 (Vidyaranyapura).	2000000	2019-20
Year	**Type of Work**	**Other Work Type**
2019 - 2020	Road	
Tender	**Work Details**	**Job No. / Work Code**
Tender	Asphalting to Roads	009-20-000085
Work Order No.	**Work Order Date**	**Period of Extention**
BBMP/EE/BTP/WO/22/2021-22	03/08/2021	
Defect Liability Period From	**Defect Liability Period To**	**Multiple road involved with the same Job No/ Work Code #**
25/04/2022	24/04/2023	No

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
M/s. SMLP Asphalts B.B. Umesha		0.00
Phone No.	**E-Mail ID**	
9886213563		

Assistant Executive Engineer
Vidyaranyapura Sub Division
B.B.M.P, Bangalore - 97

Field Inspection Details

Number of Trees	Any Other Information	Name
0		E Eranna

Date of Inspection	Remarks
18/05/2022	

Category	Image	Photo Remark
Drain Condition		This photo seems out of range
Footpath Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Segment End		This photo seems out of range.
Segment Start		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	S.P.Ranganath	18/05/2022	17/06/2022	As proposed
SE	G R Devendra Nayak	18/05/2022	17/06/2022	Forwarded
EE	MOhan Das H T	18/05/2022	17/06/2022	Forward
AEE	Shivakumar M Goudar	18/05/2022	17/06/2022	Verified
AE	E. Eranna	18/05/2022	17/06/2022	Mobile Verification Done
AE	E. Eranna	18/05/2022	17/06/2022	Forward

Assistant Executive Engineer
Vidyaranyapura Sub Division
B.B.M.P, Bangalore - 97

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
YELAHANKA	9	Vidyaranyapura
Street ID	**Street Name**	**Significant Landmark**
W0735	4th Main Rd	Houses
Segment No.	**Total Length (m)**	
9/S-W0735/S113813	33.83	

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	33.83	77.573010	13.066100	77.573082	13.066397	1st Main	Dead End

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Improvements and Asphalting to Roads at KVS Layout, 1st & 2nd Cross, Dhanalakshmi Layout in Ward No. 09 (Vidyaranyapura).	2000000	2019-20
Year	**Type of Work**	**Other Work Type**
2019 - 2020	Road	
Tender	**Work Details**	**Job No. / Work Code**
Tender	Asphalting to Roads	009-20-000085
Work Order No.	**Work Order Date**	**Period of Extention**
BBMP/EE/BTP/WO/22/2021-22	03/08/2021	
Defect Liability Period From	**Defect Liability Period To**	**Multiple road involved with the same Job No/ Work Code #**
25/04/2022	24/04/2023	No

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
M/s. SMLP Asphalts B.B. Umesha		0.00
Phone No.	**E-Mail ID**	
9886213563		

Vidyaranyapura Sub Division
B.B.M.P Bangalore - 97

Field Inspection Details

Number of Trees	Any Other Information	Name
0		E Eranna

Date of Inspection	Remarks
18/05/2022	

Category	Image	Photo Remark
Drain Condition		This photo seems out of range.
Footpath Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Segment End		This photo seems out of range.
Segment Start		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	S.P.Ranganath	18/05/2022	17/06/2022	As proposed
SE	G R Devendra Nayak	18/05/2022	17/06/2022	Forwarded
EE	Mohan Das H T	18/05/2022	17/06/2022	Forward
AEE	Shivakumar M Goudar	18/05/2022	17/06/2022	Verified
AE	E. Eranna	18/05/2022	17/06/2022	Mobile Verification Done
AE	E. Eranna	18/05/2022	17/06/2022	Forward

Zone: YELAHANKA **Ward No:** 9 **Ward Name:** Vidyaranyapura **Street ID:** W0735

Date: 18/05/2022 Time: 16:21:53 RH20220518162153

Assistant Executive Engineer
Vidyaranyapura Sub Division
B.B.M.P, Bangalore - 97